



Connections

JF4MIXTE Standard connection for TSMA assembly (tubing $\varnothing 4 \times 6 \text{mm}$). To be used on drip pipe. Hole size on supply pipe : 4 mm



JCP4 Standard connection for P4 riser or P4 assembly (tubing $\varnothing 4.4 \times 7 \text{mm}$). To be used on drip pipe. Hole size on supply pipe : 4 mm




JCP6 Standard connection for P6 assembly (tubing $\varnothing 6 \times 10 \text{mm}$). To be used on PEBD or drip pipe. Hole size on supply pipe : 4 mm



JCP10J Standard connection for S10 stake or P10 riser (tubing $\varnothing 11 \times 15$). To be used on PEBD or drip pipe. Hole size on supply pipe : 6 mm



JCP10D Quick fit connection for S10 stake or P10 riser. Sold with one plug (tubing $\varnothing 11 \times 15$). To be used on PEBD or drip pipe. Hole size on supply pipe = 6 mm



COSER Metal clamp for pipe \varnothing : 5-7 / 16 / 20 / 25 / 32 mm

